

# Operations & Maintenance Inspection Report

PROJECT: SOME PROJECT

**NUMBER OF OBSERVATIONS: 1**

**NUMBER OF CORRECTIONS: 0**

**Date:** Dec 14, 2018

**Start Time:** 10:25


**Inspection Type:** Monthly

**Inspector:** John Doe

**End Time:** 12:15

**Precipitation Status:** None

## OVERVIEW MAP



 Project Area       General Observation       Corrective Action       Sample Collection       Other

**OBSERVATION 1: GENERAL OBSERVATION**

**Time Recorded:** 11:56

**BMP Type:**


**Location Description:** Mobility Hub

**Observation Notes:** Site in compliance with SWPPP.

**OBSERVATION 1 PHOTO**



**OBSERVATION 1 LOCATION**



© 2018 Microsoft Corporation, © 2018 DigitalGlo... Powered by Esri

- Project Area
- ◆ General Observation
- ◆ Corrective Action
- ◆ Sample Collection
- ◆ Other